

Z20T Hotswap Maintenance

Hotswap #	Maintenance completed	Maintenance completed	
	1	2	
1			
2	Hinge tighten, replaced top part of hinge (black) <i>Completed by Tash</i> 3/6/21		
3			
4			
5	replaced back cover <i>Completed by Jason 7/6/21</i>		
6			
7			
8			
9	replaced hinge <i>Completed by Jason 2/6/21</i>	no repair required <i>Completed by Tash</i> 17/06/21	
10	tightend hinges/ replaced keyboard end <i>Completed by Tim 1/6/21</i>		
11			
12	no repair required <i>Completed by Tim 1/6/21</i>		
13			
14	hinge tightened, screws replaced on base <i>Completed by Jason 8/6/21</i>		
15	Replaced keyboard <i>Completed by Tim 1/6/21</i>		
16	Tightend Hinges <i>Completed by Tim 1/6/21</i>		
17	Hine tighten <i>Completed by Tash</i> 17/06/21		
18			
19	Tightened hinge <i>Completed by Jason 2/6/21</i>	Nothing to fix <i>Completed by Tash</i> 3/6/21	
20	Hinge tighten <i>Completed by Tash</i> 10/6/21		
21	Tightened hinge <i>Completed by Jason 2/6/21</i>	Replaced keyboard, kb not responding or transferring power <i>Completed by Tash</i> 3/6/21	
22	Tightened hinge, replaced B key <i>Completed by Jason 2/6/21</i>		
23			
24	back cover replaced (swapped hole machine), hinge tightened <i>Completed by Jason 10/6/21</i>		
25			

26	nothing to fix <i>Completed by Jason 3/6/21</i>	Replaced back cover <i>Completed by Tash 10/6/21</i>	
27			
28			
29	hinge only slightly loose- tightened hinge precautionarily <i>Completed by Tash 3/6/21</i>		
30			
31		no repair required <i>Completed by Tash 17/06/21</i>	
32			
33			
34	Tightened Hinges/ reimaged <i>Completed by Tim 1/6/21</i>	L,O,C keys reported to be not working - worked fine when tested. <i>Completed by Tash 3/6/21</i>	
35	Hinge tighten <i>Completed by Ron 15/6/21</i>		
36			
37	No repair needed <i>Completed by Tim 1/6/21</i>	Hinge tighten <i>Completed by Tash 10/6/21</i>	
38	Back cover replaced <i>Completed by Tim 7/6/21</i>	Hinge tighten <i>Completed by Tash 10/6/21</i>	
39			
40	tightened hinges/ replaced "o" key <i>Completed by Tim 1/6/21</i>		
41	nothing to fix <i>Completed by Jason 2/6/21</i>	nothing to fix <i>Completed by Tash 3/6/21</i>	
42	Tightened hinge <i>Completed by Jason 2/6/21</i>	Replaced power button <i>Completed by Tash 3/6/21</i>	
43			
44			
45			
46			
47	replaced keyboard charging port/suggested sticker replacement <i>Completed by Tim 1/6/21</i>	tightened hinge, replaced back cover (required swapping entire machine) <i>Completed by Jason 8/6/21</i>	no repair needed <i>Completed by Tash 17/06/21</i>
48			
49			
50	hinge tightened <i>Completed by Jason 2/6/21</i>	Power button replaced <i>Completed by Tash 3/6/21</i>	
51	no repair required <i>Completed by Tim 1/6/21</i>	no repair required <i>Completed by Tash 3/06/21</i>	

52			
53			
54	no repair required <i>Completed by Jason 2/6/21</i>	no repair required <i>Completed by Tash 17/06/21</i>	
55			
56	Hinge tighten <i>Completed by Tash 10/6/21</i>		